Denton County ? Aerobic Septic System

Testing and Reporting Form (Rev. 2021 layout) · File with Denton County Environmental Health · Testing every 4 months

Property owner: Marcus Webb
Property address: 8820 Teasley Ln, Denton, TX
OSSF permit number: DN-2021-1187
Date of test: 2026-02-16
Report type: Routine
Inspected by: Dana Whitfield
Maintenance firm: ClearWater OSSF Services (demo)
MP license number: MP-004812

Inspection findings

Component	Operational	Inoperative	Component	Operational	Inoperative
Aerators	X		Chlorine Supply	X	
Filters	X		Electrical Circuits	X	
Irrigation Pumps	X		Distribution System	X	
Recirculation Pumps	X		Sprayfield Vegetation	X	
Disinfection Device	X		Other	N/A	

Lids secure: Before service: secure · After service: secure

Tests

Chlorine residual (total): 0.5 mg/L — Method: Grab

Dana Whitfield — 2026-02-16

Maintenance provider signature (§285.7(b)(3)) — Date

Generated from the recorded inspection ? verify before filing. Filing remains the provider's responsibility.